ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	10	Dodda Bommasandra

Street ID	Street Name	Significant Landmark
W0107, W0104, W0113, W0100	Subhash Chandra Bose Lyt, NA, 3rd Crs	SHBG House at Chamundeshwari layout

Segment No.	Total Length (m)
10/C-W0107/S104911	132.37

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	65.49	77.556191	13.065053	77.556771	13.064889	W0107	W0113
2	66.88	77.556091	13.064764	77.556681	13.064590	W0107	W0113

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Roads Drain and Covering Slabs at SHBG House at Chamundeshwari layout in ward no 10 Doddabommasandra Vidyaranayapura Sub-Division Ye	1500000	2015

Year	Type of Work	Other Work Type
2015 - 2016	Asphalting	

Tender	Work Details	Job No. / Work Code
Tender	Improvements to Roads Drain and Covering Slabs at SHBG House at Chamundeshwari layout in ward no 10 Doddabommasandra Vidyaranayapura Sub-Division Yelahanka zone	010-16-000021

Work Order No.	Work Order Date	Period of Extention
EE/BTP/BBMP/E-PMT/WO/323/2015-16	24/03/2016	90 DAYS

Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
24/03/2016	23/03/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
ASWATHNARAYANA		0.00

Phone No.	E-Mail ID
9448034435	

Field Inspection Details

Number of Trees	Any Other Information	Name
3		MADHAVA RAO

Date of Inspection	Remarks
15/09/2016	COMPLETED

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Zone:	YELAHANKA	Ward No:	10	Ward Name:	Dodda Bommasandra	Street ID:	W0107, W0104, W0113, W0100

Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	15/09/2016	15/10/2016	COMPLETED
SE	VASU K M	15/09/2016	15/10/2016	COMPLETED
EE	YARAPPA REDDY	15/09/2016	15/10/2016	COMPLETED
AEE	SHIVAKUMAR	15/09/2016	15/10/2016	COMPLETED
AE	MADHAV RAO	15/09/2016	15/10/2016	COMPLETED
AE	MADHAV RAO	15/09/2016	15/10/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 10 **Ward Name:** Dodda Bommasandra **Street ID:** W0107, W0104, W0113, W0100